


TRANSMISSION ARMS POLE MOUNTING HOLE ZONE

Figure 2

No knot shall exceed a diameter of 1" for close grain, or 1- $\frac{1}{4}$ " for dense grain, in these two sections.



No knot in the inner zone shall exceed $\frac{3}{4}$ " diameter.

Pole mounting hole